Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Client ID: 50005DE8992

Work Order Name: WO/50005DE8992/1
Work Order Type: Weatherization
Audit Name: Audit (248)

CLIENT INFORMATION

Client Name: Address:

Alt. Client ID:

AGENCY INFORMATION

Agency: Delta Human Resource Agency
Agency Phone: (901) 476-5226

Address: P. O. Box 634

Fax: (901) 476-5258

, TN

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Measures

	Measure 1 Infil	tration Redctn			Componen	its			Inspected
C	comment Weathe	erstrip Door1, Door2, Doo	r3; Replac	ce 15"x	32" Crawl S	pace Doo	r		
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Miscellaneous Supplies	Infiltration Reduction	Each	1					
C	Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								
	Measure 2 DW	H Pipe Insulation			Componen	nts			Inspected
C	Comment				Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty		
1	Insulation				Offic Cost	i Otai	٠.,	Unit Cost	Total
2		DHW Pipe Insulation	Each	1		Total		Unit Cost	Total
	Labor	DHW Pipe Insulation DHW Pipe Insulation	Each Each	1		7 otal		Unit Cost	Total
C	Labor Other Detail							Unit Cost	Total
								Unit Cost	Total
								Unit Cost	Total
			Each	1	e Sub Total:			Unit Cost	Total
			Each	1					Total

Report Run On: 5/28/2010

Measure 3 Rep Comment	lace A/C			Componen Estimated			Inspecte	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Actual Unit Cost	Total
1 Cooling Equipmen	-	Each	1					
2 Labor	Window A/C -	Each	1					
Other Detail								
				e Sub Total:			Sub Total:	
Measure 4 Rep	lace Htg. System			Componen	ts HS1			Inspecte
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Heating Equipment	Space Heater - 15 kBtu/h NG Existing, 41 - 57 kBtu/h NG Post	Each	1					
2 Labor	Space Heater - 15 kBtu/h NG Existing, 41 - 57 kBtu/h NG Post	Each	1					
Other Detail			1			1		
			Measur	e Sub Total:] .	Sub Total:	
Field Notes:								

	Measure 5 DWH omment	H Tank Insulation			Componen	ts		ı	Inspected
C	Omment				Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equipment	DHW Tank Insulation	Each	1					
2	Labor	DHW Tank Insulation	Each	1					
C	Other Detail								
				Measur	e Sub Total:			Sub Total:	
L									
	Measure 6 CO I	Monitor is Needed			Componen				Inspected
С	omment		Units	Qfv	Estimated		- Ofv	Actual	
C #		Description / Comment	<i>Units</i> Each	Qty 1	•		Qty		Inspected Total
C #	omment Material / Labor Health and Safety	Description / Comment			Estimated		Qty	Actual	
C # 1	omment Material / Labor Health and Safety Items	Description / Comment CO monitor	Each	1	Estimated		Qty	Actual	
C # 1	omment Material / Labor Health and Safety Items Labor	Description / Comment CO monitor	Each	1	Estimated		Qty	Actual	
C # 1	omment Material / Labor Health and Safety Items Labor	Description / Comment CO monitor	Each	1	Estimated		Qty	Actual	
C # 1	omment Material / Labor Health and Safety Items Labor	Description / Comment CO monitor	Hour	1	Estimated			Actual	

Report Run On: 5/28/2010

# Materi 1 Health Items	ial / Labor n and Safety	Pr heater is present in this Description / Comment Equipment	s home. <i>Units</i>	Qty	Estimated			Actual	
Health Items Labor	n and Safety		Units					Actual	
1 Health Items 2 Labor	n and Safety		Units	Qtv					
Items 2 Labor		Equipment		4.7	Unit Cost	Total	Qty	Unit Cost	Total
			Each	1					
Other De		Labor	Hour	1					
	etail								
				Measur	e Sub Total:			Sub Total:	
Measu Comme		all Bathroom Exhaust F	an		Componen				Inspecte
_					Estimated	 -		Actual	
# Materi	ial / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
l Health Items	n and Safety	Bathroom exhaust fan	Each	1					
2 Labor		Labor	Hour	1					
Other De	e <i>tail</i>								
				Measur	e Sub Total:			Sub Total:	
	Notes:								
Field N									

Measure 9 Insta	all Kitchen Exhaust Fan	l		Componen	ts		ı	Inspected
Comment								
				Estimated	<u>'</u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
 Health and Safety Items 	Kitchen exhaust fan	Each	1					
2 Labor	Labor	Hour	1					
Other Detail						1		
			Measur	e Sub Total:		•	Sub Total:	
Measure 10 Smo	ke Detector is Needed			Componen	ts			Inspected
				Estimated	<u>'</u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
 Health and Safety Items 	Smoke detector	Each	1					
2 Labor	Labor		1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:			Measur	e Sub Total:			Sub Total:	

Report Run On: 5/28/2010